
## **Smoke and Dye Testing Summary**

### **High Level Sewershed**

| Run Summa | ry <del></del> |                   |                     |             |                     |                       |                 |
|-----------|----------------|-------------------|---------------------|-------------|---------------------|-----------------------|-----------------|
| Test ID   | Test Type      | Date<br>Inspected | Company /<br>Super. | Blower MH   | Ground<br>Condition | Notification<br>Made? | Total<br>Length |
| S1028-112 | Smoke          | 10/16/2008        | ADS/TM              | S11GG_020MH | Dry                 | Yes                   | 956.39          |



# **Smoke and Dye Testing Summary**

## **High Level Sewershed**

| Run Summar | у ——      |                   |                     |             |                     |                       |                 |
|------------|-----------|-------------------|---------------------|-------------|---------------------|-----------------------|-----------------|
| Test ID    | Test Type | Date<br>Inspected | Company /<br>Super. | Blower MH   | Ground<br>Condition | Notification<br>Made? | Total<br>Length |
| S1028-112  | Smoke     | 10/16/2008        | ADS/TM              | S11GG_020MH | Dry                 | Yes                   | 956.39          |

|            |             |               | Length   | Diameter |
|------------|-------------|---------------|----------|----------|
| pe ID      | Upstream MH | Downstream MH | (ft)     | (In)     |
| 11GG_035G1 | S11GG_035MH | S11GG_008MH   | 75.82651 | 8        |
| 11GG_031G1 | S11GG_031MH | S11GG_035MH   | 86.08276 | 8        |
| 11GG_016G1 | S11GG_016MH | S11GG_008MH   | 142.7251 | 8        |
| 11GG_046G1 | S11GG_046MH | S11GG_012MH   | 81.70744 | 8        |
| 11GG_008G1 | S11GG_008MH | S11GG_020MH   | 221.5515 | 8        |
| 11GG_013G1 | S11GG_013MH | S11GG_046MH   | 97.82341 | 8        |
| 11GG_020G1 | S11GG_020MH | S11GG_013MH   | 250.6766 | 8        |

#### **Observations & Photos**

No smoke was observed during this test.